
Main reinforcing bar
This mortar broken away when shutter removed
Concrete column
Shutter with "letter box" at top
Potential sites for new anodes
Spalled region broken out and filled with repair mortar