


Fig no : 7.2.2



- Multiplying factors  
 factor for  
 0.04 iron ore  
 0.07 gypsum  
 0.10 oil  
 0.12 sand  
 0.21 clay  
 0.22 coal

scale

A : 1cm = 200/400/600 TPD

B : 1cm = 100/200/300 TPD

Example :

clinkering capacity : 7500 TPD

coal required : 1650 TPD