



This area has bonded aramid (Kevlar) fibre to give additional resistance to punching shear. It is kept below the water line because it is not attractive.

This area has two layers of bonded woven glass rovings. They become completely transparent when wetted with epoxy.