



Display of transit time of pulse

Emitter and receiver are identical

Test sample

Calibration bar with known pulse transit time

Grease needed to ensure there is no air gap between emitter/receiver and sample which would block acoustic contact